

October 2016, Eldorado do Sul - Brazil

DATACOM notifies the launching of the 14.10.4 firmware version for the DM4000 and DM4100 series products. This document contains the changes from firmware version 14.10.2.

### **Firmware Upgrading Procedure**

- The firmware upgrade in chassis or stacking devices must be performed in all interface cards simultaneously, observing the supported versions, in order to avoid undesirable inconsistencies.
- For firmware upgrading from version 12.x (or less) to 14.x, it is required to perform a two-stages procedure, applying an upgrade to 13.8.6 (intermediate recommended version) and then to the final version 14.x.

Stage 1: firmware upgrade from version 12.x to 13.8.6 with subsequent reboot.

Stage 2: firmware upgrade from version 13.8.6 to 14.x with subsequent reboot.

- The MPLS access interfaces must not be configured with the feature QinQ external mode. An exception is a combination of untagged access with `vc-type vlan` parameter in the VPN. In this specific configuration the QinQ configuration is not overwritten by the VPN. Check the current configuration before upgrading from versions previous than 14.2 in order to avoid traffic loss due to conflicts at QinQ tag profile caused by VPN.
- The meters using srTcm and trTcm mode must be reconfigured and associated again to the respective filters after ending the firmware upgrade from versions 12.x or 13.x to version 14.x.  
In case of any doubt about the procedure contact DATACOM Technical Support.
- Previous versions of 14.2 do not support VPN TE (`mplstype te`). Firmware downgrade for those versions affects the VPNs with such configuration demanding the VPN neighbor reconfiguration.
- OSPFv3 authentication configuration is not compatible with previous versions of 13.0. During an upgrade/downgrade this parameter must be removed before starting the procedure and added after new firmware version is active.
- Be sure of removing all RSVP tunnels with ID greater than 100 (one hundred) and reduce the amount of VPLS ports to maximum eight before starting a downgrade of version 14.10.4 to a previous one older than 14.10.

- From the version 14.10.2 on the commands `ip igmp snooping flood-unknown` and `ipv6 mld snooping flood-unknown` are available only in the VLAN configuration scope. The configuration must be done individually for each VLAN that requires the disabling of flood-unknown multicast. After an upgrade/downgrade the equipment must have this configuration rebuilt because it will return to the default value of flood-unknown multicast.

### **New Features and Improvements**

- Added new logs for VPN MPLS in case of remote link access state changes.
- Changes on command `show vlan summary id` to present port-channels members.
- Added new SNMP MIB numeric fields to allow SFP/XFP modules information reading in a numeric format.
- Added new filter options to set match per TTL.
- Added new command `cfm-test-tst` to allow CFM type TST wirespeed forwarding according to RFC2544.
- Display the flood-unknown configuration status in the commands `ip igmp snooping` and `show ipv6 mld snooping output`.

**Corrections**

- Correct the MAC addresses limit when the command `switch port-security maximum` is applied to a port-channel.
- Links monitored by BFD that belongs to an OSPFv3 domain can cause system restart during occurrence of many flaps.
- Negative values are shown after executing the command `cfm delay-measurement two-way` in a port-channel interface.
- Packets from management interface are sent with VLAN innertag 3 in DM4001 devices.
- VLAN translate configuration is not applied to packets originated in CPU.
- Interfaces configuration via WEB is generating errors messages.
- Changes on the ICMP debug information to show interface encapsulation (`u:` for untagged and `t:` for tagged) and the port-channel identification, as well as the specific interface where the packet is sent/received (`PCHn unit/port`).
- Equipment allows packet forwarding from host with network different from the VLAN network directly connected if it contains another VLAN with the same host network and by which the destination is reachable.
- Correction on command `show mpls ftn` to present the unit/port of a port-channel (`PCHn`).
- Data reading correction for XFP model 377.1208.xx.
- Increase of memory consumption in units of a DM4000 chassis due to hosts audit mechanism.
- SNMP GET operations for ethernet or transceiver MIBs can cause system

restart.

- Equipment freezes during command `dump` execution when there are many installed routes.
- OSPF adjacencies flap after changing an interface configuration via DMView.
- "Power supply B fail/ok" logs are shown in DM4000 ETH4x10GX H Series board even when the power supply is normal.
- VPN traffic interruption due to link flaps or network re-convergence when there are both VPNs VLAN based and VPNs Port based configured.
- The command `show mpls l2vpn counters` can present errors in case of conflicts between internal VPN counters priority and customer filter priority.

**Compatibilities and Restrictions**

- This firmware version supports devices of DM4000 and DM4100 Family. The compatibility matrix between MPU and interface cards for DM4000 in chassis is displayed in the Annex 1.
- The usage of command `no ipv6 mld snooping flood-unknown` causes OSPFv3 adjacencies to go to down state.
- The lowest recommended DmView version to use with CESoP feature is the 8.2.
- All DM4100 devices when operating in stacking mode must use the same software license. The current software licenses available are: Bridge (L2), Router (L3) and MPLS.
- The use of VLAN 1 (default) in L2 and L3 applications is not recommended.
- Firmware downgrade is not supported to a version lower than 14.8 when the configuration contains VPN `vc-type` settings distinct on the same physical interface.
- MPLS is not supported in pizza box stacking.

- Use of RSVP services in MPLS scenarios with external memory enabled and configured to store also L3 routes requires the configuration of the `memory external-resource vlan` command. Note that the VLAN used in this command is reserved and can not be used for other purposes.
- There are some restrictions about using RSVP and MPLS traffic engineering (MPLS-TE). Consult DATACOM Technical Support for more details.
- RSVP tunnels re-convergence time below 50ms is not guaranteed on DM4100 Series.
- After a switchover can occur a VPN misbehavior if the `vc-type` contains distinct settings on the same physical interface and the access interface contains port-channel as well as the feature `LDP graceful-restart` is enabled.
- Local tunnel and RFC 3107 are not supported for the DM4100 family.
- Local Tunnel is not supported by DM4000 PWE3 H Series 32E1 module, DM4004 e DM4008.
- More than one RFC 3107 session (BGP address-family IPv4 with send-label) is only supported in the same PE when neighbors advertise different prefixes in each session.
- Metric cost and metric type manipulation in redistributed routes from RFC3107 to OSPF is not supported.
- Selective QinQ is not supported on VPN access ports for all DM4000 family.
- There may be momentary traffic loss during graceful-restart period in LDP scenarios.
- The use of enhanced mode for port-channel load balancing is not recommended because it can cause traffic shaping in interfaces with 10GB capacity.
- VRF-Lite does not allow IP addresses overlapping.
- Improvements made in CPU-Protect functionality may require a feature reconfiguration after firmware upgrade to versions higher than 14.2. Consult DATACOM Technical Support for more details.
- No support for multiple IPv6 network protection using VRRP.
- BGP IPv6 Peer-Group is not supported.
- A total of 48 control queues were added in version 14.2 allowing more accurate selection and controlling over the packets to CPU (command: `cpu-dos-protect queue`). The commands `cpu-dos-protect block arp request` and `cpu-dos-protect block reserved-multicast` were removed.
- OSPF default originate does not guarantee reasonable convergence times and can cause momentaneous traffic unavailability in a BGP full routing scenario when using VLAN link-detect.
- The command `auto-cost reference-bandwidth` should not be used in OSPFv3 configuration.
- Avoid RIP configuration with VLAN IP address using network mask /31.
- The storm control default values (multicast / broadcast / unicast) for interfaces 1GB and 10GB have been changed in version 14.6.2. In interfaces 1GB it has changed from 1000pps to 10000pps and in interfaces 10GB it has changed from 10000pps to 100000pps.
- There are some restrictions to reach the limit of 8k hosts in DM4100 L3 24P equipment. Consult DATACOM Technical Support for more details.
- The MPU384 with product code 800.0442.10 has the version 14.6 as a minimum firmware.
- DHCP Snooping database presents

- inconsistent records after releasing some client IPs right after a master switchover operation in Stacking.
- DHCP Snooping can not be used simultaneously with the features DHCP Server and DHCP Client.
  - LDP-IGP Sync presenting configuration mismatch in interfaces containing only IPv6 address.
  - The use of ECMP along with BFD or BGP can cause the fall of these protocols, when the main path drops. It can occur if the error detection interval for a BFD session that is configured in the BGP neighbor is less than 7 seconds or if the BGP holdtime is less than 21 seconds in a session session without BFD.
  - In order to change the port-channel state from shutdown to no shutdown when using LACP it also requires the changing of the interfaces state that make up the port-channel.
  - In a DM4100 equipment model ETH44GT 4GC+2XX+S it is recommended to use a maximum of 7 xSTP instances.
  - Due to the introduction of new meter modes that allow the combination of hierarchical meters to the filters it has caused an incompatibility with versions minor than 14.x in the case that meters were using srTcm and trTcm mode. Such meters are removed from the configuration during the firmware upgrade. Therefore, they must be recreated and associated again to the filters after update ending.
  - Duplicated IPv6 address is not reported by VRRPv3.
  - The feature ipfix is not released for DM4100-24P equipment.
  - It is not possible to perform a ping to broadcast addresses.
  - An equivalent protection of command `cpu-dos-protect block l3-slow-path` with the advantage of not affecting L3 protocols is the creation of a filter to allow the packets reception for the required protocol and another filter with lower priority to drop packets with TTL=1.
  - The command `dump` can take several minutes to be executed. Therefore, the CLI becomes unavailable during this period.
  - VPN get stuck after changing the MPLS capabilities of an uplink VLAN when the VLAN is in shutdown state.
  - The removal of command `switchport vlan-translate ingress` might not be effective requiring the vlan-translate rules to be also removed.
  - Versions from 14.10 on do not allow meters and filters association in case of filters with different priorities. This will cause errors during configuration.
  - Possible packet loss when incoming traffic in a port-channel composed by two or more 10GB interfaces go out through another port-channel in a different slot of a DM4004 or DM4008 chassis. The cause is that a wrong load balance mode has been used in this condition.

Get contact with DATACOM Technical Support by e-mail to [support@datacom.ind.br](mailto:support@datacom.ind.br) or via phone call (+55 51 3933 3122) in order to obtain additional information about supported features, upgrading procedures and compatibility of firmware versions, modules and accessories.

**Annex 1: Compatibility Matrix to DM4000 in Chassis**

The following table displays the compatibility between MPU and interface cards to DM4000 in chassis, for the firmware version 14.10.4:

<b>Interface Cards</b>	<b>MPU384</b>	<b>MPU512</b>
ETH24GX H Series	✓	✓
ETH24GX E Series	✓	✓
ETH24GX L Series <sup>(*)</sup>	--	--
ETH24GT H Series	✓	✓
ETH48GX H Series	✓	✓
ETH48GT H Series	✓	✓
ETH24GX+2x10GX H Series	✓	✓
ETH24GX+2x10GX E Series	✓	✓
ETH2x10GX H Series	✓	✓
ETH4x10GX H Series	✓	✓
ETH4x10GX E Series	✓	✓
PWE3 ETH20GX+32E1 H Series	✓	✓
PWE3 ETH20GX+2x10GX+32E1 H Series	✓	✓
PWE3 ETH16GX+4STM1 H Series	✓	✓
PWE3 ETH16GX+2x10GX+4STM1 H Series	✓	✓

<sup>(\*)</sup> - L Series devices is compatible only in a standalone operation through the usage of a chassis DM4001 or DM4001 L.